

ILLINOIS MARINE TOWING

2. Barge Condition and Inspection Reports – 8/1/14 – 4/2015

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2099	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Hackett Slip	08-15-2011

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: STBD WINCH AND BOW HAS MISSING WIRE.

WINDY CITY
MOTOR VESSEL


JOHN PENCRAZ
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2100	✓		Hockett Sl. P	08-15-2014




CLEAN OF:

TRASH YES NO
PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐




VOID SOUNDINGS
BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK PULLED MISSING
☒ ☐ ☐

MANWAY COVERS

IN PLACE MISSING
☒ ☐



PUMPING ENROUTE

YES NO
☐ ☐

REMARKS: ALL WINCHES ON BOW AND STERN MISSING WIRE.

PORT WINCH ON BOW HAS BROKEN STRAP.

WINDY CITY
MOTOR VESSEL

JOHN PANGRACE
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2095	✓		Hedder slip	08-15-2014

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS	
BOW	
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: PORT WINCH ON BOW MISSING WIRE

WINNY CITY
 MOTOR VESSEL

JOHN PONGRACE
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO	LOAD	EMPTY	LOCATION	DATE
C84 262	✓		Hackett slip	08-15-2014

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: PORT WINCH ON ROW 12 BROKEN AND MISSING WIRE.

BOTH WINCHES ON STERN MISSING WIRE.

WINDY CITY
MOTOR VESSEL


JOHN PONGRACE
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
ING 723	X		NRF	8-30-14

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

PORT

BOW

STERN

STBD

VOID SOUNDINGS

BOW	0
NO. 1	0
NO. 2	0
NO. 3	1"
NO. 4	7 1/2"
NO. 5	
STERN	0

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: stopped out stem tank had 1' in it

Windy City
 MOTOR VESSEL

Jim Cunningham
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 211B	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Channahon	9-14-14

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

	BOW	
	NO. 1	
	NO. 2	
	NO. 3	
	NO. 4	
	NO. 5	
	STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: COVER ON #4 Void Tank Bent and Broke From hinges NEEDS NEW COVER Accident waiting to happen, Put Tape OVER for Cation purposes

Windy City
MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 5347	X		JYF	10-2-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	D
NO. 1	1 1/2"
NO. 2	D
NO. 3	2"
NO. 4	2"
NO. 5	
STERN	2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

9'3" port Stern corner

Windy City
MOTOR VESSEL


P. Edwards
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 96012	X		SYS	10-4-14


CLEAN OF:

YES NO
TRASH ☐ ☐
PRODUCT ☐ ☐



CARGO BOX:

OPEN HOPPER ☐
STACKED ☒
SPREAD ☐
RESET COVERS ☐




VOID SOUNDINGS	
BOW	T
NO. 1	1 1/2"
NO. 2	4"
NO. 3	3"
NO. 4	2"
NO. 5	2 1/2"
STERN	T

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

Heavy Side will Strip tanks when we
have a chance

MOTOR VESSEL

Windy City

INSPECTED BY

P. Edwards

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
RCI 251	X		LTV	12-22-2014

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	7 1/2"
NO. 1	dry
NO. 2	1 1/2"
NO. 3	3"
NO. 4	2 1/2"
NO. 5	0
STERN	0

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: PUT OUT 2" pump on bow tank 7 1/2"
 And 2" pump 3 tank - 4 tank

W. J. J. J.
 MOTOR VESSEL


Robert J. J. J.
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
RC#251	<input checked="" type="checkbox"/>	<input type="checkbox"/>	LTL	12/22/14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	0
NO. 1	0-7
NO. 2	1 1/2'
NO. 3	1 1/2"
NO. 4	1/2"
NO. 5	0
STERN	0

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS:

pumped out

Wing City
MOTOR VESSEL


Robert A. Lab
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2083	X		WALSH SLIP	1/19/2015


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	<input checked="" type="checkbox"/>
NO. 1	<input checked="" type="checkbox"/>
NO. 2	<input checked="" type="checkbox"/>
NO. 3	<input checked="" type="checkbox"/>
NO. 4	<input checked="" type="checkbox"/>
NO. 5	<input checked="" type="checkbox"/>
STERN	<input checked="" type="checkbox"/>

DECK FITTINGS


OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>



REMARKS:

WINDY CITY
MOTOR VESSEL

ROY SPARROW
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Frn 98068	X		OK BOW	08-14-2014


CLEAN OF:

TRASH PRODUCT

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	6
NO. 5	✓
STERN 0	

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

Heavy corner GET TO PUT COVERS
Stack on still maybe Get Heavy-

William C
MOTOR VESSEL

Rob Derbes
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 126		<input checked="" type="checkbox"/>	IMT JACK YARD	8-24-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	1'
NO. 1	3"
NO. 2	3"
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: CHECKED OUT THE IMT 126 AND FOUND WHAT LOOKS LIKE MAYBE A FOOT OF WATER IN THE RAIR. DID STICK THE HOPPER FOUND 10" OF WATER AND 3" IN THE #1 / 2 TANK. NOT PUMPING AT THIS TIME

WILLIAM C
MOTOR VESSEL

SHAWN MAJES
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO	LOAD	EMPTY	LOCATION	DATE
RCE 259		<input checked="" type="checkbox"/>	IMT JACK YARD	8-24-19

CLEAN OF:

TRASH
PRODUCT




YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

X PIG
IRON



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐




VOID SOUNDINGS	
BOW	OK
NO. 1	9"
NO. 2	3"
NO. 3	6"
NO. 4	3"
NO. 5	5"
STERN	OK

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: CHECKED ENT RCE 259 STOCK ALL TANKS AND HOPPER.
12" IN HOPPER 9" #1 3" #2 6" #3 3" #4 5" #5
PUMPING NOT IN ROUTE.

WILLIAM C
MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 213 ^B		X	S/B WMC Ex IMT Ford	8/26/11


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	2"
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Stripping Hopper
4"

William C.
MOTOR VESSEL

Nick Moskus
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING2034	X		South Side	8/31/14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

	BOW		VOID SOUNDINGS
	BOW		1
	NO. 1		9"
	NO. 2		2"
	NO. 3		2"
	NO. 4		4"
NO. 5	3"		
STERN	3"		

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

William C
MOTOR VESSEL


[Signature]
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 5437	X		South Side	8/31/14


CLEAN OF:

	YES NO
TRASH	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	<input type="checkbox"/>
NO. 1	<input type="checkbox"/>
NO. 2	1"
NO. 3	4"
NO. 4	X
NO. 5	X
STERN	1"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS:

William C
MOTOR VESSEL


[Signature]
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX2045	X		South side	8/31/14


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	<input type="checkbox"/>
NO. 1	<input type="checkbox"/>
NO. 2	<input type="checkbox"/>
NO. 3	<input type="checkbox"/>
NO. 4	<input type="checkbox"/>
NO. 5	<input checked="" type="checkbox"/>
STERN	<input type="checkbox"/>

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 2108	X		South Side	9-1-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	0
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	X
STERN	3

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

William C
MOTOR VESSEL

Pete Edwards
INSPECTED BY

ING 2034

X

S. Chicago

9-3-2014

X
X

X

9'6"

8'6"

7"

6"

5"

4"

3"

2"

1"

9'5"

8'6"

X

X

X

Pumped Voids = Bow- #1 - #2 - #3 & 4

William C.

D. KEHM

BARGE CONDITION & INSPECTION REPORT


BARGE NO	LOAD	EMPTY	LOCATION	DATE
OR-7011	X		Channahon	8-14-2019

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	<i>dry</i>
NO. 1	1/2"
NO. 2	<i>dry</i>
NO. 3	2"
NO. 4	2"
NO. 5	6"
STERN	1"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Midwest Prairie
MOTOR VESSEL


B. Galtbreath
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Ing 2024	✓		Rapps Fleet	8/28/14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	0
NO. 1	0
NO. 2	1 1/2
NO. 3	1
NO. 4	S
NO. 5	0
STERN	0

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Attempted to go into the Number Two tank to begin shingling the barge, hole is where the hopper and bottom of hopper meet, was unable to get any shingles in place. During the attempt at shingling the gas meter alarm went off and I exited the tank.

Midwest Pride
MOTOR VESSEL

James Wexelberg
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING-2024	X		Channahon	8-29-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Midwest Pride
MOTOR VESSEL

Galbraith / Wood
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING-1601	X		Channahon	9-7-2014

CLEAN OF:


TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

6 wing tanks

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

Bow - 1"
 1 - 1"
 2 - 4"
 3 - 0
 4 - 9 1/2"
 5 - 16 1/2"
 6 - 1/2"
 STERN - 1"



VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3 <input checked="" type="checkbox"/>
NO. 4 <input checked="" type="checkbox"/>
NO. 5 <input checked="" type="checkbox"/>
STERN <input checked="" type="checkbox"/>

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

Midwest Pride
 MOTOR VESSEL

Hartman / Ealey
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO	LOAD	EMPTY	LOCATION	DATE
OB-4843	X		Channahon	9-7-2014

CLEAN OF:

YES NO
 TRASH ☒ ☐
 PRODUCT ☒ ☐

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Midwest Pride
 MOTOR VESSEL

Blattner / Ealey
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Talk-1386	X		Channahon	7-22-14

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

8'7"

9'1" 9'7"

VOID SOUNDINGS

BOW	dry
NO. 1	1"
NO. 2	5 1/2"
NO. 3	3"
NO. 4	1.5"
NO. 5	
STERN	dry

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Michael L. Lunde
 MOTOR VESSEL

Garrett / Lunde
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
0A-1237	X		Channahon	9-7-2014

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Midwest Taida
 MOTOR VESSEL


Channahon
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PCI 257	X		Channahon	1/29/15


CLEAN OF:

YES NO
 TRASH ☒ ☐
 PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW	6"
NO. 1	1"
NO. 2	2'4"
NO. 3	2'4"
NO. 4	2'4"
NO. 5	14"
STERN	3"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS:

Midwest Pride
 MOTOR VESSEL


David C. Williams
 INSPECTED BY Elafmuth

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 2030	X		NRF	8-09-14

CLEAN OF:

TRASH ☐ YES ☐ NO
 PRODUCT ☐ ☐



CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

PORT

BOW

STERN

STBD

VOID SOUNDINGS


BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: FOUND OLD REPAIR PATCH-WELD CRACKED AND
PATCH DETACHING. VERY TOP OF STB. STERN
CORNER, HIGH ABOVE WATER LINE.

P.S. MAY HAVE BEEN REPORTED BEFORE.
IT IS PART OF 3/8 TOW FOR SAM FLEMING

MARY C.
 MOTOR VESSEL

[Signature]
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN 995414	<input checked="" type="checkbox"/>	<input type="checkbox"/>	TRD	08-09-2014

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	River level
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	
STERN	0

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Seen cd IN fleet with 9 10% draft
 ✓ OUT found lower River level.

P/O 2 inch pump
 NIGHT CREW: WE PUMPED AND SHINGLED 3 HOLES IN BOW
 TANK. GOT IT ALMOST STOPPED. P.K.

MARY C
 MOTOR VESSEL

Robert C. Denbes
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T13975	-	<input checked="" type="checkbox"/>	SFS	8-28-014

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	2'
NO. 1	2 1/2
NO. 2	2
NO. 3	0
NO. 4	0
NO. 5	0
STERN	2'

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Sdld STERN QUARTER KVEL HAS A LARGE DENT ON THE side of the barge. Above the dent is a 7 inch long CRACK.

MARY C

MOTOR VESSEL

WILLIAM E. JACKSON
 INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 7079	X		MMH	9-3-14

CLEAN OF:


TRASH
PRODUCT

YES NO
☒ ☐
☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID
SOUNDINGS

BOW	1/2"
NO. 1	9"
NO. 2	7"
NO. 3	5"
NO. 4	6 1/2"
NO. 5	7 1/2"
STERN	1/2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: Place 2-2" gas pumps out Strip
a voids 1-5

Mary C
MOTOR VESSEL

Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 75149		X	OX low	9-7-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	1/2"
NO. 1	1"
NO. 2	1/2"
NO. 3	1 1/2"
NO. 4	1"
NO. 5	
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Put out 2" gas pump strip out
hopper

Mark C
MOTOR VESSEL


Tammy Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IND 75005		X	OXbow	9-7-14




CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




VOID SOUNDINGS	
BOW	1 1/2"
NO. 1	1/2"
NO. 2	3 1/2"
NO. 3	4"
NO. 4	5"
NO. 5	
STERN	4"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: Put out 2" gas pump strip hopper & void tanks

Mary C
 MOTOR VESSEL

Tony Lopez
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ENG 5713	X		oxbow	9-15-14

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

The diagram shows a cross-section of a barge. The main body is labeled 'BOW' at the top and 'STERN' at the bottom. The width at the bow is 8'9" and at the stern is 8'11". The height at the bow is 8'6" and at the stern is 9'2". The diagram also shows the 'PORT' and 'STBD' (starboard) sides. To the right of the diagram is a table for 'VOID SOUNDINGS'.

VOID SOUNDINGS	
BOW	0
NO. 1	4"
NO. 2	3 1/2"
NO. 3	2 1/2"
NO. 4	4"
NO. 5	
STERN	1/2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: Place 2- gas pump + strip voids

Mary C
 MOTOR VESSEL

Tony Lopez
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T 13855	X		TRD	9-29-14

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:


OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW



STBD



STERN

VOID SOUNDINGS

BOW	1/2"
NO. 1	7"
NO. 2	1/2"
NO. 3	Ø
NO. 4	Ø
NO. 5	1/2"
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Max C
MOTOR VESSEL


Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T 13855	X		TRD	9-29-14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	1/2"
NO. 1	7"
NO. 2	1/2"
NO. 3	Ø
NO. 4	Ø
NO. 5	1/2"
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

May C
MOTOR VESSEL

Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN 9 36434	X		TRD	9-29-14

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	1"
NO. 1	1/2"
NO. 2	0
NO. 3	4"
NO. 4	1"
NO. 5	1"
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Mack C
MOTOR VESSEL

Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 5713	X		oxbow	9-15-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Place 2- gas pump + strip voids

Mary C
MOTOR VESSEL

Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 133	X		NRF	11/10/2014

CLEAN OF:


TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW	1 1/2"
NO. 1	1/2"
NO. 2	0
NO. 3	1"
NO. 4	1/2"
NO. 5	
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☒

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: #4 starboard void cover is broken off the hinge

Wally C
 MOTOR VESSEL


Tony Lopez
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
0A 5159	X		NRF # 300	12-01-14




CLEAN OF:

YES NO
 TRASH ☐ ☐
 PRODUCT ☐ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: THIS BARGE IS FOR S/B McFARLIN. IT IS A LEAKER, HAIRLINE CRACK LEFT AFTER SHINGLEING. IMPOSSIBLE TO STOP THE LEAK 100%. IT HAD 16" OF WATER AT THE TIME OF PICK-UP.

MARY C.
 MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
0A 5159	X		NRF # 300	12-01-14




CLEAN OF:

TRASH ☐ YES ☐ NO
 PRODUCT ☐ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




VOID SOUNDINGS
BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: THIS BARGE IS FOR S/B McFARLIN. IT IS A LEAKER, HAIRLINE CRACK LEFT AFTER SHINGLEING. IMPOSSIBLE TO STOP THE LEAK 100%. IT HAD 16" OF WATER AT THE TIME OF PICK-UP.

MARY C.
 MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
0A 5159	X		NRF # 30D	12-01-14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>




CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS


BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>



PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: THIS BARGE IS FOR S/B McFARLIN. IT IS A LEAKING,
HAIRLINE CRACK LEFT AFTER SHINGLEING. IMPOSSIBLE TO
STOP THE LEAK 100%. IT HAD 16" OF WATER
AT THE TIME OF PICK-UP.

MARY C.

MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 6538	X		NRF	2-10-15

CLEAN OF:

	YES NO
TRASH	<input checked="" type="checkbox"/> <input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/> <input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	0
NO. 1	2"
NO. 2	1"
NO. 3	2"
NO. 4	2"
NO. 5	1"
STERN	1"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Macy C
MOTOR VESSEL

Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 6538	X		URF	2-10-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	0
NO. 1	2"
NO. 2	1"
NO. 3	2"
NO. 4	2"
NO. 5	1"
STERN	1"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Mary C
MOTOR VESSEL


Tony Lopez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 5813	X		Lower Crane	02-25-2015


CLEAN OF:

TRASH YES NO
PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: P/O 3" pump start on 4 TANK will pump
OUT 3-1 TANKS ALSO

MARYC
MOTOR VESSEL


Robert I Derbys
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 5813	X		Water Crane	02-25-2015

CLEAN OF:

	YES	NO
TRASH	X	
PRODUCT		



CARGO BOX:

OPEN HOPPER	X
STACKED	
SPREAD	
RESET COVERS	

PORT	BOW		STBD
	8/6	9/3	
STERN			
		VOID SOUNDINGS	
		BOW 0	
		NO. 1 5"	
		NO. 2 2"	
		NO. 3 5 1/2"	
		NO. 4 6"	
		NO. 5	
		STERN 1"	

DECK FITTINGS

OK	PULLED	MISSING
X		

MANWAY COVERS

IN PLACE	MISSING
X	

PUMPING ENROUTE

YES	NO
X	

REMARKS: P/O 3" pump start on 4 TANK will pump
OUT 3-1 TANKS ALSO

MARYC
MOTOR VESSEL

Robert (Derbis)
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN 65864	X		Ox Bow	03-02-2015

CLEAN OF:


TRASH
PRODUCT

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID
SOUNDINGS

BOW	0
NO. 1	3 1/2"
NO. 2	3"
NO. 3	3 1/2"
NO. 4	3"
NO. 5	
STERN	

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

REMARKS:

p/o 2" pump on 8 TANK start there will
pump out all 4 wind TANKS 1-4 (WAA
still HRS TO GET COVERS PUT ON CD

MARIC
MOTOR VESSEL

Robert L. Reslar
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN 5864	X		OXBOW	03-02-2015

CLEAN OF:




TRASH
PRODUCT

YES NO
☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐




VOID SOUNDINGS	
BOW	0
NO. 1	3 1/2"
NO. 2	3"
NO. 3	3 1/2"
NO. 4	3"
NO. 5	
STERN	

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: p/o 2" pump on 4 TANK start there will
pump out all 4 wind TANKS 1-4 (can
still hrs to get covers put on cd

MARC
MOTOR VESSEL

Robert L. Reslar
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN135431	X		OXBOW	03-26-2015

CLEAN OF:




TRASH
PRODUCT

YES NO
☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS	
BOW	0
NO. 1	4 1/2"
NO. 2	3 1/2"
NO. 3	2 1/2"
NO. 4	3 1/2"
NO. 5	
STERN	0

DECK FITTINGS

OK PULLED MISSING
☐ ☐ ☐

MANWAY COVERS

IN PLACE MISSING
☒ ☐

PUMPING ENROUTE

YES NO
☒ ☐

REMARKS: p/o 2" pump start on 2 TANK will pump
OUT ALL 4 TANKS once GET covers on
MIGHTS GO OVER 9/6 feet Draft

M9C4C
MOTOR VESSEL


Robert C. Barber
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN/35431	X		545	03-26-2015


CLEAN OF:

TRASH ☐ YES ☐ NO
 PRODUCT ☐ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW	0
NO. 1	0
NO. 2	0
NO. 3	2"
NO. 4	1/2"
NO. 5	
STERN	0

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

After pumped out

Mary C
 MOTOR VESSEL


Robert C. Decker
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN135431	X		OXBOW	03-26-2015




CLEAN OF:

TRASH YES NO
PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW	0
NO. 1	4 1/2"
NO. 2	3 1/2"
NO. 3	2 1/2"
NO. 4	3 1/2"
NO. 5	
STERN	0

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: P/O 2" pump start on 2 TANK will pump
OUT ALL 4 TANKS once get covers on
MIGHTS GO OVER 9/16 foot Draft

MARYC
MOTOR VESSEL


Robert C. Beal
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
IN/35431	X		545	03-26-2015

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

 PORT	BOW	 STBD																
	8/5		8/7															
	STERN																	
<table border="1"> <tr> <th colspan="2">VOID SOUNDINGS</th> </tr> <tr> <td>BOW</td> <td>0</td> </tr> <tr> <td>NO. 1</td> <td>0</td> </tr> <tr> <td>NO. 2</td> <td>0</td> </tr> <tr> <td>NO. 3</td> <td>2"</td> </tr> <tr> <td>NO. 4</td> <td>1/2"</td> </tr> <tr> <td>NO. 5</td> <td></td> </tr> <tr> <td>STERN</td> <td>0</td> </tr> </table>			VOID SOUNDINGS		BOW	0	NO. 1	0	NO. 2	0	NO. 3	2"	NO. 4	1/2"	NO. 5		STERN	0
VOID SOUNDINGS																		
BOW	0																	
NO. 1	0																	
NO. 2	0																	
NO. 3	2"																	
NO. 4	1/2"																	
NO. 5																		
STERN	0																	

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS:

After pumped out

Mary C
MOTOR VESSEL

Robert C. Decker
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 20 94	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Chencho	8-16-14

CLEAN OF:

TRASH
PRODUCT


YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>




CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW 5"
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Strip 5" NON contaminated water Bow Tank

Lemont Trader
MOTOR VESSEL

Shawn Davis
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
78 2218	X		N.R.F	9-9-14

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	
NO. 1	2 1/2"
NO. 2	2"
NO. 3	2"
NO. 4	1"
NO. 5	2"
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: TO HEAVY TO TRANSPORT TO CITANNATION, LEFT
IT BEHIND IN LEMONT

14:30

LEMONT TRADER
 MOTOR VESSEL

TOSH + DERRICK
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
COY 407 ^B		<input checked="" type="checkbox"/>	Int Lemont	9/20/14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

<p>PORT</p>	<p>BOW</p>	<p>STBD</p>	VOID SOUNDINGS
			BOW 3 1/2"
			NO. 1 3 1/4"
			NO. 2
			NO. 3
			NO. 4
NO. 5			
			STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Discovered
5 1/2"
Bow / 3 1/4" #1
Upon Plug
Stripped

Lemont Trader
MOTOR VESSEL


David Perez
Dan Sundberg
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PB 2341		✓	Jdlet ^{EX} Windy City	9-27-14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	<input checked="" type="checkbox"/>	MISSING	<input type="checkbox"/>
----	-------------------------------------	---------	--------------------------

MANWAY COVERS

IN PLACE	<input checked="" type="checkbox"/>	MISSING	<input type="checkbox"/>
----------	-------------------------------------	---------	--------------------------

PUMPING ENROUTE

YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
-----	--------------------------	----	-------------------------------------

REMARKS:

1. STARBOARD HALF CAVEL Broken in Two
 2. ~~COMBING~~ RAIL Damage 20' FROM STERN PORT Side
 3' By 6" section Broke AND Push Down (No Damage TO BEAMS)

Lemont Trader
 MOTOR VESSEL

Shawn M...
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 122	X		Rapp	11-3-2014

CLEAN OF:

TRASH ☐ YES ☐ NO
PRODUCT ☐ ☐

CARGO BOX:

OPEN HOPPER ☐
STACKED ☐
SPREAD ☒
RESET COVERS ☐



VOID SOUNDINGS

BOW	dry
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

9'5" corner - part of S/A jaw

Needs TRIM

Lemont TRADER

MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PB2351		X	Ottawa	12-20-14




CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS	
BOW	6 FT
NO. 1	1"
NO. 2	1/2"
NO. 3	0
NO. 4	0
NO. 5	
STERN	1"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

Hopper has ICE

PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: Two large cracks on STBD knuckle where knuckle meets tank #1 and runs around the #2 - Bottom draft mark is pumping from wall of #1 to about 6-8 FT of RAKE is Buckled - 6" crack on floor outside of STBD corner RAKE and another 6" crack with a hole size of half dollar next to it. Shingled and it leaking slow 1-2" of water every 6-8 hours

Leman Trader
 MOTOR VESSEL

David & Pete
 INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
SAVG 215	X		Int Channahon	12/26/14

CLEAN OF:




	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>

COKE LOAD



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

SOK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

LARGE DENT IN HULL
 BARGE - STBD SIDE - APPROX
 4' Long
 Pushed in
 about 10" to 12"
 HALF moon SHAPED

Lemont Trader
 MOTOR VESSEL

INSPECTED BY John Hansen


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PB2356	X		Int Chann	12/26/14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>


coke Load




for S/B Tow

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

WINCH BROKE LOOSE
STBD, STERN CORNER
LAYING ON DECK
BY CENTER KAVEL-

Lemont Trader
MOTOR VESSEL

John Hanson
INSPECTED BY Nickmoskos

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Int 123	X		Int Chann	12/26/14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>

coke
load

for S/B TOW

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

<p>PORT</p>	<p>BOW</p>	<p>STBD</p>	VOID SOUNDINGS
			BOW
			NO. 1
			NO. 2
			NO. 3
			NO. 4
NO. 5			
	STERN		

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

BIG DENT @ APPROX 50' BACK
FROM BOW END — RUNS ABOUT
5' LONG — CREASED @ DECK

Lemont Trader
MOTOR VESSEL


John Hanson
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CAY 402		<input checked="" type="checkbox"/>	X WALKER HIGGS	1-4-15


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW
NO. 1
NO. 2 <input checked="" type="checkbox"/>
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: #2 MANWAY COVER PORT SIDE BROKE OFF
 HINGES

Remont Tradit
 MOTOR VESSEL

A. Boyden
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Cox 2048		X	FROM WALTER HAYSTAN	1-4-15

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4 X
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: #4 MANHOLE COVER IS THERE BUT IS BROKE off FROM HINGES STARBOARD SIDE

Lemont Trader
MOTOR VESSEL

D. GORDON
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 215		X	MALLET Hagestad	1-4-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	
STACKED	
SPREAD	
RESET COVERS	



VOID SOUNDINGS

BOW
NO. 1
NO. 2 X
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: #2 Manhole cover port side broke off hinges

Lemont Thaden
MOTOR VESSEL

M WALLACE
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBY 2840		<input checked="" type="checkbox"/>	Int Lemont	1-21-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	4"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Discovered 4" stern
tank upon PLUP
STRIPPED

Lemont Trader
MOTOR VESSEL

Nick Moskos
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CB4 2768		X	N/B EX	1-25-15

CLEAN OF:

TRASH ☒ YES ☐ NO
PRODUCT ☐ ☒


EX
CORE



USAGE HENN

CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW	1/2"
NO. 1	
NO. 2	
NO. 3	1/2"
NO. 4	1/2"
NO. 5	1/2"
STERN	1/2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

4" HOPPER
upon pump Black water

Lemont Trader
MOTOR VESSEL

David Perez
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 5455		<input checked="" type="checkbox"/>	ARTCO Ottawa	3-8-13

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID
SOUNDINGS

BOW	18"
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

DISCOVERED

18" Bow
Tank upon
PLUP

STREPPED

Leamont Trader

MOTOR VESSEL

INSPECTED BY Dan Sandberg

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 5000	X		LTV S-Chicago	8-15-19

CLEAN OF:

YES NO
TRASH ☐ ☐
PRODUCT ☐ ☐

CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW	D
NO. 1	1"
NO. 2	1"
NO. 3	1 1/2"
NO. 4	2"
NO. 5	
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Checked drafts for S/B low - 9'2" corner
Left in the fleet

MOTOR VESSEL

INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 210	X		Mobil Coke	8-18-14

CLEAN OF:

TRASH
PRODUCT


YES NO
☒ ☐ ☐ ☐



CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

☒
☐
☐
☐



VOID
SOUNDINGS

BOW	D
NO. 1	3 1/2"
NO. 2	D
NO. 3	D
NO. 4	3"
NO. 5	
STERN	

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: Stripped out #1 + #4 wing tanks 8'3" Bow 8'-11"

Drift after Pumped

Still over Drift

8'10" stern 9'5"

Eileen C

MOTOR VESSEL

M. Wetzel

INSPECTED BY

IMT 0087

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 15454	X		Bayou / Kanlia	8/24/14

CLEAN OF:

TRASH ☐ YES ☐ NO
PRODUCT ☐ ☐

CARGO BOX:

OPEN HOPPER ☐
STACKED ☒
SPREAD ☐
RESET COVERS ☐



DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

Before
REMARKS: Pumped #2 W.T. Had 2 1/2' feet water
Bow Draft 9'7" stern 8'10"


After
Stopped to 3" - #2 W.T. Tank.
Bow - 9'3 1/2" Suffer Reading Alarms
went off! C.O. 33
Hole in Wing Tank here it Looking Pretty good over 20.2
cant see it. Not safe to enter int.
Esken C. James Bell
MOTOR VESSEL INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 4775	<input checked="" type="checkbox"/>	<input type="checkbox"/>	South Chicago	8-24-14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	Dry
NO. 1	12 in
NO. 2	8 in
NO. 3	1 1/2 in
NO. 4	2 1/2 in
NO. 5	2 1/2 in
STERN	Dry

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: port stern Drafting 9'4" port Bow 9'0" Feet
 STBD stern 9'10" STBD Bow 9'12" Pumping number 1 + number 2
 tanks Pumping Time (1730 - 2100)

Stopped ALL Tanks out: P. Bow - 9'0" S. Bow 9'4"
 S. STERN 9'7" P. STERN 9'1"

Eileen C.
 MOTOR VESSEL


James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
CB 406	X		CO. 1	7/24/11


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	<input checked="" type="checkbox"/>
NO. 1	<input type="checkbox"/>
NO. 2	<input type="checkbox"/>
NO. 3	<input type="checkbox"/>
NO. 4	<input type="checkbox"/>
NO. 5	<input checked="" type="checkbox"/>
STERN	<input checked="" type="checkbox"/>

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS:

24 Sacks Dry. 4.11 and Draft

MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T 13596	✓		walsh slip	8-27-11


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




VOID SOUNDINGS	
BOW	Dry
NO. 1	Dry
NO. 2	Dry
NO. 3	3"
NO. 4	1 1/2"
NO. 5	Dry
STERN	2

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>



PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

Fibanc
MOTOR VESSEL


James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN/6 2210	X		Walsh	8/27/14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	<input checked="" type="checkbox"/>
NO. 1	<input checked="" type="checkbox"/>
NO. 2	<input checked="" type="checkbox"/>
NO. 3	<input checked="" type="checkbox"/>
NO. 4	<input checked="" type="checkbox"/>
NO. 5	<input checked="" type="checkbox"/>
STERN	<input checked="" type="checkbox"/>

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

E. I. Krenel
MOTOR VESSEL

James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
BB 2218	<input checked="" type="checkbox"/>	<input type="checkbox"/>	walsh slip	8-27-14

CLEAN OF:

	YES NO
TRASH	<input checked="" type="checkbox"/> <input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/> <input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	Dry
NO. 1	2 1/2"
NO. 2	2 1/2"
NO. 3	2"
NO. 4	1
NO. 5	2
STERN	Dry

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Filem c
MOTOR VESSEL


James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
CBY 403	X		Walsh	8/27/14


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	1 1/2"
NO. 1	✓
NO. 2	✓
NO. 3	✓
NO. 4	✓
NO. 5	✓
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

Eileen
 MOTOR VESSEL


James Ball
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 2272	X		walsh	8/27/14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	1"
NO. 1	2"
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	1"
STERN	1 1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

E. Leons
MOTOR VESSEL


June Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2046	X		Walsh	8/27/14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	Dry
NO. 1	Dry
NO. 2	Dry
NO. 3	Dry
NO. 4	Dry
NO. 5	Dry
STERN	2

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

Eileen C
MOTOR VESSEL


James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 5469	<input checked="" type="checkbox"/>	<input type="checkbox"/>	walsh slip	8-27-14


CLEAN OF:

YES NO
 TRASH ☒ ☒
 PRODUCT ☒ ☒



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW	Dry
NO. 1	Dry
NO. 2	Dry
NO. 3	Dry
NO. 4	Dry
NO 5	
STERN	Dry

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

Eileen C
 MOTOR VESSEL


James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ING 2108	X		walsh	8/27/14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	Ø
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	Ø
NO. 5	Ø
STERN	Ø

DECK FITTINGS


OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>



REMARKS:

Eileen
MOTOR VESSEL


James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ENG 1459	X		Lva/sh	8/22/14


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW	3
NO. 1	3
NO. 2	2
NO. 3	0
NO. 4	0
NO. 5	
STERN	3 1/2

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

Eileen C
 MOTOR VESSEL

James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 7079	X		Lakes + Rivers	8/28/14



CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

All Tanks pumped



VOID SOUNDINGS

BOW	1"
NO. 1	8 1/2"
NO. 2	7"
NO. 3	7 1/2"
NO. 4	1/2"
NO. 5	1/2"
STERN	1"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Pumped out #1 - #2 - #3 w. Tanks

Now

MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PB 2354	X		N.R.F. Lemont	8/30/14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	3/4"
NO. 1	D
NO. 2	D
NO. 3	D
NO. 4	D
NO. 5	D
STERN	D

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: Slight leak to Port

Elkan C
MOTOR VESSEL

Brett Kirdack
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Rci 253	X		ChL-River FLT	9/04/14

CLEAN OF:


TRASH
PRODUCT

YES NO
☐ ☒

Coke Load

CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



DECK FITTINGS

OK PULLED MISSING
☐ ☐ ☐

MANWAY COVERS

IN PLACE MISSING
☐ ☐

PUMPING ENROUTE

YES NO
☐ ☐

REMARKS: Draft Reading Before Pumping

8'6" 9'4 1/2"

8'6" 9'4 1/2"

Draft Reading After Pumping W.T.

8'7" 9'2 1/2"

8' 9'3"

STIMPS #3. 6" - #5. 5"

E. Lee G

MOTOR VESSEL

Brett Gruber

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CDX 2045	X		Cal River / LTV	9/04/14

CLEAN OF:

YES NO
TRASH ☐ ☒
PRODUCT ☐ ☒

CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW	D14
NO. 1	D14
NO. 2	D14
NO. 3	D14
NO. 4	D14
NO. 5	D14
STERN	D14

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: Bow winches not working

ALL Wing Tanks are Dry

E. Keri C

MOTOR VESSEL

Inspected by
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMAT 109	X		Sheds / K. n. m.	9/03/14

CLEAN OF:

YES NO
TRASH ☒ ☐
PRODUCT ☒ ☐

CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS	
BOW	6'
NO. 1	1'
NO. 2	Dry
NO. 3	Dry
NO. 4	Dry
NO. 5	Dry
STERN	Dry

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: Stripped out Bow 3" Pump
6-8 Pin holes Port Bow Knuckles Shingle 4
Stripped out Still slow Leaking Watch it: Recharge water
Diets After Pumping Bow 9'4" - STERN 9'7"
Pumping Time (1830 2045)

Eden C
MOTOR VESSEL

James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO	LOAD	EMPTY	LOCATION	DATE
Ing 1457	X		SH Bell slip	9/08/14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: Check Drifts & Stuck Tanks

Pumped out W.T's. Bow 4 1/2" - #1-8" - STERN 30"

Eileen C
MOTOR VESSEL

Brett Kirbnol
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
OR 4775	X		Bayou / Kinder	9/08/14

CLEAN OF:

YES NO
 TRASH ☐ ☐
 PRODUCT ☐ ☐

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	Dry
NO. 1	5"
NO. 2	1 1/2"
NO. 3	Dry
NO. 4	4 1/2"
NO. 5	Dry
STERN	4"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Cancelled Pick-up per Mike Blaska
 Check Drafts & Stuck ALL TANKS

Eileen C
 MOTOR VESSEL

James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
RCI 256 ^B	X		Shed / Kinda	9/8/14

CLEAN OF:


TRASH
PRODUCT

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID
SOUNDINGS

BOW	4"
NO. 1	2"
NO. 2	2 1/2"
NO. 3	2"
NO. 4	1/2"
NO. 5	9"
STERN	2 1/2"

DECK FITTINGS

OK PULLED MISSING

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

MANWAY COVERS

IN PLACE MISSING

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------

PUMPING ENROUTE

YES NO

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------

REMARKS:

ALL W.T. Readings + Drafts

Fuller
MOTOR VESSEL


James Bell
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBY 443	X		Walsh Slip	9-11-14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	2"
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	Ø
NO. 5	Ø
STERN	Ø

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: 9'4" Stern end on both sides, no water found.
Needs *TRIM JOB*

Eileen C
MOTOR VESSEL

Mike Wetzel
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IWG 1947	X		Walsh Slip	9-11-14

CLEAN OF:

TRASH ☒ YES ☐ NO

PRODUCT ☒ YES ☐ NO


CARGO BOX:

OPEN HOPPER ☒

STACKED ☐

SPREAD ☐

RESET COVERS ☐



VOID SOUNDINGS	
BOW	0
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	
STERN	0

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

Three heavy corners - ^{*}Trim Job^{*}

MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
IMT 101	X		S. Chicago	9-11-14


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	2"
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	1/2"
NO. 5	N/A
STERN	Ø

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

Eileen C
 MOTOR VESSEL

Josh Ealey
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T13600	X		Walsh Slip	9-11-14

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	4"
NO. 1	1"
NO. 2	1"
NO. 3	2"
NO. 4	2"
NO. 5	2"
STERN	0

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: Overdraft corners Port & Stbd Sern and Stbd Bow.
 Pumped bow tank of 4" of water. Needs* TRIM JOB*

Eileen C.

MOTOR VESSEL

Mike Wetzel


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CAX 2027	X		Walsh Slip	9-14-14


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	D
NO. 1	D
NO. 2	D
NO. 3	D
NO. 4	D
NO. 5	D
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS:

1- 9'-3" corner - pull ld. from S. Chicago

MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
WUG 1459	X		Walsh Slip	9-14-14

CLEAN OF:


TRASH
PRODUCT

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID SOUNDINGS

BOW	10"
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	4"

DECK FITTINGS

OK PULLED MISSING

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

MANWAY COVERS


IN PLACE MISSING

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------

PUMPING ENROUTE

YES NO

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------



REMARKS: Strip out bow tank - enter + check for Leaks
Found shingles in port bow, about 4' high in the seam of the first I-beam. No leaks seemed present.

Eileen C.
MOTOR VESSEL

Mike W. [Signature]
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INT 26489	X		LTV. S. Chicago	9-16-14

CLEAN OF:


TRASH
PRODUCT

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID
SOUNDINGS

BOW	1"
NO. 1	4"
NO. 2	4'3"
NO. 3	3'
NO. 4	2 1/2"
NO. 5	4 1/2"
STERN	2"

DECK FITTINGS

OK
PULLED
MISSING

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-------------------------------------	--------------------------	--------------------------

MANWAY COVERS

IN PLACE
MISSING

<input checked="" type="checkbox"/>	<input type="checkbox"/>
-------------------------------------	--------------------------

PUMPING ENROUTE

YES
NO

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------

REMARKS: Stripped out #5 wing
checked for S/R tow then canceled

Eileen C
MATAR VESSEL


J. Ealey
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CAX 2046	X		Walsh	9-16-14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	D
NO. 1	
NO. 2	D
NO. 3	D
NO. 4	D
NO. 5	D
STERN	2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: over draft Stern - Trim Job

MOTOR VESSEL _____ INSPECTED BY _____


BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
DW015454	X		Skyway	9-20-14

CLEAN OF:

TRASH
PRODUCT


YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID SOUNDINGS


BOW	7
NO. 1	D
NO. 2	8"
NO. 3	D
NO. 4	1"
NO. 5	
STERN	D

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐


MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐



REMARKS: set up 2" pump on #2 wing + strip

Drafts after stripping

water in the hopper - unable to pump into product piles
left the lead in the fleet

Eileen C

MOTOR VESSEL

M. Wetzel


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
RCI 256	X		LTV S. Chicago	10-24-14


CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	3"
NO. 1	1"
NO. 2	2"
NO. 3	2"
NO. 4	1"
NO. 5	8"
STERN	4"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: Set up pump to strip stern - #5

Eileen C
MOTOR VESSEL

L. Lettler
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
RCI 251	X		Ox bow	10-24-14

CLEAN OF:


TRASH
PRODUCT

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID SOUNDINGS

BOW	1"
NO. 1	β
NO. 2	β
NO. 3	β
NO. 4	β
NO. 5	β
STERN	1"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: Over Draft down Stb. side no water to pump

MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBX 2057	X		Walsh Slip	10-27-14

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	D
NO. 1	
NO. 2	P
NO. 3	P
NO. 4	P
NO. 5	P
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

9'1" across the stern

Eileen C.
MOTOR VESSEL


L. L. L.
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
PB 2218	X		Channahon	12-04-14


CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	D
NO. 1	1 1/2"
NO. 2	1"
NO. 3	1/2"
NO. 4	1/2"
NO. 5	1/2"
STERN	D

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: for S/O Elizabeth Lane to need OK
to put in tow

Elizabeth Lane
MOTOR VESSEL


L. Little
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
PB 2356	X		Lemont	12-5-14




CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




VOID SOUNDINGS	
BOW	
NO. 1	
NO. 2	
NO. 3	
NO. 4	
NO. 5	
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>



PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: Stb. Stern winch is broken off it's mounting
and laying on it's side

Eileen C
 MOTOR VESSEL


L. Little
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
212 5470		X	S. Chicago	1-17-85


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☐ YES ☒ NO




CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




PORT



BOW

STERN



STBD

VOID SOUNDINGS


BOW	6"
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	1
STERN	0

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: approx. 6" of ice in the back of the
 bow void - some coke on port stern corner
 cleaned up with broom + shovel

Eileen C
 MOTOR VESSEL

L. L. L. L.
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBY402	✓		Walsh	

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	D
NO. 1	1"
NO. 2	D
NO. 3	D
NO. 4	D
NO. 5	D
STERN	

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: 1 over draft corner

MOTOR VESSEL

INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 214	X		Channahon	1-26-15

CLEAN OF:


TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☒ damage

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: # 3 wing tank cover is missing the hinge pin
 cover is just sitting on top of man hole
 should be able to put 4 dogs on to make lake ready

E. L. Hume

MOTOR VESSEL

L. L. Hume


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IN126449		<input checked="" type="checkbox"/>	Lemont	1-27-15




CLEAN OF

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	3"
NO. 1	<input checked="" type="checkbox"/>
NO. 2	<input type="checkbox"/>
NO. 3	<input checked="" type="checkbox"/>
NO. 4	<input type="checkbox"/>
NO. 5	<input checked="" type="checkbox"/>
STERN	3"

DECK FITTINGS


OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>



REMARKS: Bow and stern had 3" of water.
Pumped barge, no leaks present.

E. J. ...
MOTOR VESSEL

N. V. ...
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO	LOAD	EMPTY	LOCATION	DATE
Ino 85057	X		Leansat	2-9-15

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW
NO. 1
NO. 2
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS: Maybe a 2" indent on starboard bow and some paint scratch couldn't tell nothing that that from previous wear and tear on large

Eileen C
MOTOR VESSEL

Jackson Simpson
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD EMPTY	LOCATION	DATE
JBX 2638	X	YO 20 slip	3-27-15

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐

VOID SOUNDINGS

BOW	11.1
NO. 1	3.2
NO. 2	4.5
NO. 3	11.2
NO. 4	11.2
NO. 5	5.1
STERN	11.2

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: has a good size dent along side about
 50 ft from the bow about right where the JH
 wing tank is

Elmer C
 MOTOR VESSEL

James Cunningham
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
RCI 252		<input checked="" type="checkbox"/>	Channahon	3-7-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW
NO. 1
NO. 2 12"
NO. 3
NO. 4
NO. 5
STERN

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Number 2 tank fills a foot of water in around 8 hours

Aggie C
MOTOR VESSEL

Travis L. L. L.
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
ABS 125	X		Marblehead S. Chicago	3-19-15

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ ☐

CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☒
 RESET COVERS ☐



VOID SOUNDINGS

BOW	D
NO. 1	2"
NO. 2	1/2"
NO. 3	2"
NO. 4	1 1/2"
NO. 5	1/2"
STERN	T

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: 9' 1" corner check to see if we can pick up

Apple C
 MOTOR VESSEL


J. Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INW015451	X		Skyway	3-20-15


CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☐
 STACKED ☒
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	D
NO. 1	D
NO. 2	P
NO. 3	P
NO. 4	D
NO. 5	
STERN	P

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: 9'3" bow - check with office -

Agate C
 MOTOR VESSEL

J. Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IWO 75072	K		Skyway/S. Chicago	3-20-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input checked="" type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	D
NO. 1	1"
NO. 2	1 1/2"
NO. 3	1/2"
NO. 4	1 1/2"
NO. 5	
STERN	1"

DECK FITTINGS		
OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS	
IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: 9'1" stb. bow cover - need OK to P/W

Agyle C
MOTOR VESSEL

J. Bell
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBY 474	X		Walsh	3-24-15

CLEAN OF:

TRASH PRODUCT


YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>



CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>



VOID SOUNDINGS

BOW	1 1/2"
NO. 1	D
NO. 2	15 1/2"
NO. 3	D
NO. 4	D
NO. 5	D
STERN	1 1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Set up 2" pump to strip out # 2 wing tank

Regie C
MOTOR VESSEL

R. Kulas
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
C64 2006	X			

CLEAN OF:

TRASH ☐ YES ☐ NO
 PRODUCT ☐ ☐

CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	D
NO. 1	D
NO. 2	D
NO. 3	D
NO. 4	D
NO. 5	D
STERN	1"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

REMARKS: 9'1" port Stern corner - call for OK to pull

Aggie C
 MOTOR VESSEL


R. Kulas
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
CBY 411	X		Walsh	04/04/2015


CLEAN OF:

TRASH YES NO
 PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	Ø
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	Ø
NO. 5	Ø
STERN	Ø

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Over draft on Bow end. No water in wing tanks

Aggie C
 MOTOR VESSEL


James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 131	X		Walsh	4/4/2015


CLEAN OF:

YES NO
 TRASH ☒ ☐
 PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS


BOW	Ø
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	Ø
NO. 5	Ø
STERN	1 1/2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS:

Over draft

Aggre C
 MOTOR VESSEL

James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 17430	X		Walsh	4/4/2015

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS	
BOW	1"
NO. 1	Ø
NO. 2	Ø
NO. 3	Ø
NO. 4	Ø
NO. 5	Ø
STERN	Ø

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Overdraft

Aggiec
 MOTOR VESSEL

James Bell
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT131	X		WALSH SLIP	4/9/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	0'1"
NO. 1	0'1"
NO. 2	0'1"
NO. 3	0'1"
NO. 4	0'1"
NO. 5	0'1"
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS: OVER DRAFT ON STERN

Aggie C.

MOTOR VESSEL

LARRY LEFFLER

INSPECTED BY

IMT 0137

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT131	X		WALSH SLIP	4/9/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	0''
NO. 1	0''
NO. 2	0''
NO. 3	0''
NO. 4	0''
NO. 5	0''
STERN	1/2''

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: OVER DRAFT ON STERN

Agia G.
MOTOR VESSEL

LARRY LEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 131	X		WALSH SLIP	4/12/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	<input checked="" type="checkbox"/>
NO. 1	<input checked="" type="checkbox"/>
NO. 2	<input checked="" type="checkbox"/>
NO. 3	<input checked="" type="checkbox"/>
NO. 4	<input checked="" type="checkbox"/>
NO. 5	<input type="checkbox"/>
STERN	<input checked="" type="checkbox"/>

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

AGGIE C
MOTOR VESSEL

LARRY HEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
IMT 131	X		WALSH SLIP	4/12/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	0
NO. 1	0
NO. 2	0
NO. 3	0
NO. 4	0
NO. 5	—
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

AGGIE C
MOTOR VESSEL

LARRY LEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
1118530	✓		Lemont - TRD	4-12-15

CLEAN OF:


	YES NO
TRASH	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/> <input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW	4"
NO. 1	1 1/2"
NO. 2	1 1/2"
NO. 3	1 1/2"
NO. 4	1"
NO. 5	1 1/2"
STERN	2 1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

Aggie C
MOTOR VESSEL

HARRY LEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
W126465	X		WALSH SUP	4/12/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	2
NO. 1	7
NO. 2	4
NO. 3	4
NO. 4	0
NO. 5	3.5
STERN	2.5

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: PUMPED TANKS 1, 2, 3, AND 5

AGGIE C
MOTOR VESSEL

LARRY LEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
1N126465	X		WALSH SLIP	4/12/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	2
NO. 1	7
NO. 2	4
NO. 3	4
NO. 4	0
NO. 5	3.5
STERN	2.5

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: PUMPED TANKS 1, 2, 3, AND 5

AGIE C
MOTOR VESSEL

LARRY LEFFLER
INSPECTOR

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
118530	✓		Lemont TRD	4-18-13

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

CARGO BOX:


OPEN HOPPER	<input type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW



STERN



STBD

VOID SOUNDINGS

BOW	4"
NO. 1	1 1/2"
NO. 2	1 1/2"
NO. 3	1 1/2"
NO. 4	1"
NO. 5	1 1/2"
STERN	2 1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Aggie C
MOTOR VESSEL

HARRY L. CPELER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
740-94030	✓		hemlock - TRD	4/12/15

CLEAN OF:


	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>




PORT



BOW

STERN



STBD

VOID SOUNDINGS

BOW	1"
NO. 1	2"
NO. 2	3 1/2"
NO. 3	3 1/2"
NO. 4	4
NO. 5	N/A
STERN	1 1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

ABGIEC
MOTOR VESSEL

LARRY HEFFLER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
240-21030	✓		hemlock - TRD	4/12/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	1"
NO. 1	2"
NO. 2	3 1/2"
NO. 3	3 1/2"
NO. 4	4
NO. 5	N/A
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>

REMARKS:

AGSIEC
MOTOR VESSEL

LARRY KEEFER
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 15432	X		Skyway S. Chicago	4-13-15

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☐
 STACKED ☒
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS	
BOW	
NO. 1	1 1/2"
NO. 2	7"
NO. 3	Dry
NO. 4	Dry
NO. 5	
STERN	1"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: 9'12" corner - Set up 2" pump + strip #2 wing tank

Aggie C
 MOTOR VESSEL

R. Kulas
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
W126453	X		SKYWAY	4/13/15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input checked="" type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS	
BOW	1/2"
NO. 1	3 1/2"
NO. 2	2.5"
NO. 3	2.5"
NO. 4	1 3/4"
NO. 5	0"
STERN	3.5"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: good Drafts strip out tanks over 3"
#1 wing stern tank

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INO 15432	X		Skyway S. Chicago	4-13-15

CLEAN OF:

TRASH YES NO
PRODUCT ☒ ☐

CARGO BOX:

OPEN HOPPER ☐
STACKED ☒
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW
NO. 1 1 1/2"
NO. 2 7"
NO. 3 Dry
NO. 4 Dry
NO. 5
STERN 1"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: 9'2" corner - Set up 2" pump + strip #2 wing tank

Aggie C
MOTOR VESSEL

R. Kulas
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T13843	X		Walsh	4-15-15

CLEAN OF:

	YES	NO
TRASH	<input type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	4"
NO. 1	4"
NO. 2	6"
NO. 3	5"
NO. 4	D
NO. 5	4"
STERN	1/2"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS:

Argie C
MOTOR VESSEL


R. Kulas
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
INB 5835	X		Bayou	4-15-15

CLEAN OF:




TRASH YES NO
PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER
STACKED
SPREAD
RESET COVERS

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>



VOID SOUNDINGS


BOW
NO. 1 3"
NO. 2 3"
NO. 3 3"
NO. 4 3"
NO. 5
STERN

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: good on Drafts Set up 3" pump + strip wing tanks for fish barrier

MOTOR VESSEL


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Inv 96082		X	OXbow	8-11-14




CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO



CARGO BOX:

OPEN HOPPER ☐
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐




VOID SOUNDINGS	
BOW	2"
NO. 1	4"
NO. 2	4 1/2"
NO. 3	1 1/2"
NO. 4	4"
NO. 5	4 1/2"
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐



PUMPING ENROUTE

YES ☒ NO ☐

REMARKS: Put out 2" gas pump we have only one
 on the Albert. William C will put more
 pumps out

Albert C
 MOTOR VESSEL

Tony Lopez
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
I No 75108	X		MMH	8-25-14

CLEAN OF:

YES NO
 TRASH ☒ ☐
 PRODUCT ☒ ☐

CARGO BOX:

OPEN HOPPER ☒
 STACKED ☐
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	2"
NO. 1	3"
NO. 2	3"
NO. 3	3"
NO. 4	2"
NO. 5	
STERN	2"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☒

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS:

Albert C
 MOTOR VESSEL

Tony Lopez
 INSPECTED BY

BARGE CONDITION & INSPECTION REPORT




BARGE NO.	LOAD	EMPTY	LOCATION	DATE
Ing 6552		X	OX Bow - Lemont	9-16-14

CLEAN OF:

	YES NO
TRASH	<input checked="" type="checkbox"/> <input type="checkbox"/>
PRODUCT	<input type="checkbox"/> <input checked="" type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>



VOID SOUNDINGS

BOW	2"
NO. 1	5"
NO. 2	6"
NO. 3	4"
NO. 4	4"
NO. 5	4"
STERN	3"

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Barge did have water but as they loaded it was just all running to a couple of tanks cause of the list.

ALBERT C
MOTOR VESSEL

Tim ford
INSPECTED BY


BARGE CONDITION & INSPECTION REPORT

BARGE NO	LOAD	EMPTY	LOCATION	DATE
IN107030	X		TRD. Levee	10/04/14

CLEAN OF:

TRASH ☐ YES ☐ NO

PRODUCT ☐ ☐




CARGO BOX:

OPEN HOPPER ☐

STACKED ☐

SPREAD ☐

RESET COVERS ☐



VOID SOUNDINGS


BOW	1 1/2"
NO. 1	2 1/2"
NO. 2	2 1/4"
NO. 3	2 1/2"
NO. 4	2 1/2"
NO. 5	—
STERN	1 1/4"

DECK FITTINGS

OK ☐ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☐ MISSING ☐



PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: Port side overdraft 9'5" - 9'4 1/2"

Stripping ALL Wing Tank. "see Void Soundings"

2 - 2" Pumps Time: (1915 -)

Pumped out Brought up to 9'2" least draft

ALBERT C.

MOTOR VESSEL

Brett Kirby


INSPECTED BY

BARGE CONDITION & INSPECTION REPORT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
T-13855	X		Ox Bow. 2.4.19.6.1	10/06/14 @ 1715


CLEAN OF:

YES NO
TRASH ☒ ☐
PRODUCT ☒ ☐



CARGO BOX:

OPEN HOPPER ☒
STACKED ☐
SPREAD ☐
RESET COVERS ☐



VOID SOUNDINGS

BOW	1"
NO. 1	4"
NO. 2	Dry
NO. 3	Dry
NO. 4	Dry
NO. 5	Dry
STERN	Dry

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

PUMPING ENROUTE

YES ☒ NO ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

REMARKS: Lead Drafting 9'0" All GROSS

#1 Wing Tank had 4" water stopped out

ALBERT C
MOTOR VESSEL

Brett Kirbach
INSPECTED BY

BARGE CONDITION & INSPECTION REPORT


BARGE NO.	LOAD	EMPTY	LOCATION	DATE
W126453	X		SKYWAY	4/13/15

CLEAN OF:

TRASH ☒ YES ☐ NO
 PRODUCT ☒ YES ☐ NO

CARGO BOX:

OPEN HOPPER ☐
 STACKED ☒
 SPREAD ☐
 RESET COVERS ☐



VOID SOUNDINGS

BOW	1/2"
NO. 1	3 1/2"
NO. 2	2.5"
NO. 3	2.5"
NO. 4	1 3/4"
NO. 5	0"
STERN	3.5"

DECK FITTINGS

OK ☒ PULLED ☐ MISSING ☐

MANWAY COVERS

IN PLACE ☒ MISSING ☐

PUMPING ENROUTE

YES ☐ NO ☐

REMARKS: good Drafts strip out tanks over 3"
 #1 wing stern tank

BARGE CONDITION & INSPECTION REPORT

IMT

BARGE NO.	LOAD	EMPTY	LOCATION	DATE
210 B		✓	Maquette Hill top	5-5-15

CLEAN OF:

	YES	NO
TRASH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRODUCT	<input type="checkbox"/>	<input checked="" type="checkbox"/>

CARGO BOX:

OPEN HOPPER	<input checked="" type="checkbox"/>
STACKED	<input type="checkbox"/>
SPREAD	<input type="checkbox"/>
RESET COVERS	<input type="checkbox"/>

	BOW		<h3>VOID SOUNDINGS</h3> <table border="1"> <tr><td>BOW</td><td>2"</td></tr> <tr><td>NO. 1</td><td>0"</td></tr> <tr><td>NO. 2</td><td>3 1/2"</td></tr> <tr><td>NO. 3</td><td>1 1/2"</td></tr> <tr><td>NO. 4</td><td>1"</td></tr> <tr><td>NO. 5</td><td></td></tr> <tr><td>STERN</td><td>7"</td></tr> </table>	BOW	2"	NO. 1	0"	NO. 2	3 1/2"	NO. 3	1 1/2"	NO. 4	1"	NO. 5		STERN	7"
	BOW			2"													
NO. 1	0"																
NO. 2	3 1/2"																
NO. 3	1 1/2"																
NO. 4	1"																
NO. 5																	
STERN	7"																
	STERN																

DECK FITTINGS

OK	PULLED	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PUMPING ENROUTE

YES	NO
<input type="checkbox"/>	<input type="checkbox"/>

MANWAY COVERS

IN PLACE	MISSING
<input checked="" type="checkbox"/>	<input type="checkbox"/>

REMARKS: Walkway have product they need to be swept

Albert C
MOTOR VESSEL

Tony Lopez
INSPECTED BY